


FASGLITTER Must Be Mixed With FASKOAT #40200



**Pour 1 Vial Of
FASGLITTER
Into 1 Bottle Of
FASKOAT**

**Shake Well Before
Use And Often During
Painting - Flakes Will
Settle To Bottom And
Coverage May Be
Uneven.**

Custom mix metallics like the pros! Our ultra fine metal flake powder is specially formulated to give you the highest quality results. Mix one vial per bottle of FASKOAT #40200. **Do Not Mix Directly With Paint.** Spray 1-4 thin, even coat(s) using an airbrush. When painting inside a clear body: Let dry and back it up with any color for a dazzling metallic effect (dark paint colors will make FASGLITTER stand out the best). You can use any color glitter for any color paint. Pearl and Silver are the most popular and can be used to make any paint color look metallic with nice flakes. Visit www.parmapse.com for more info.

FASKOAT Clear is designed to be carrier for FASGLITTER and is part of the FASKOLOR non-toxic and water-based line of hobby paints. Use an airbrush with a Medium or Large tip and spray at 40-70 psi. Water-based paint requires more air pressure than thinner-based paints. You can also mix up less than 1 bottle of FASGLITTER for smaller projects, just be sure to use the ratio of 1 to 1 as a starting point. You can mix different FASGLITTER colors together. Airbrush bottle adapters (#40242) are also available so you can "plug" your bottle of FASKOAT/FASGLITTER into most airbrushes.

When your FASGLITTER is mixed and ready to spray, test spray on scrap material to adjust air pressure for best results. Hold the airbrush 12-19 inches away from the surface you are painting and spray light coats. Coat until you are satisfied with the coverage. Use a hair type blow dryer to speed up drying time between coats and let dry before you back with your final color(s) of paint. Our painting instructions usually refer to painting on the inside of "clear" bodies. If you are painting the outside of any other surface, you would simply paint it the color(s) and let dry. You can then airbrush FASGLITTER over it. FASKOAT/FASGLITTER produces a finish without a high gloss. After it is completely dry it can be topcoated with a clear urethane or enamel spray paint for gloss and protection. Be careful and spray light coats of FASGLITTER using this method. If you spray FASGLITTER on too heavy it may make your final color hazy. We suggest testing on scrap material to assure best results before using on your final project(s).

Clean Up: Spray warm water through your airbrush immediately after use and clean the airbrush completely with soap and water and/or FASKLEANER #40202 when finished painting. Pull out the needle and remove the head of your airbrush and clean completely for best results. 8-06 1-0400